



## TECHNICAL NOTE

### **Model HI 6500 Series**

#### **Update advisory notice for Firmware version 1.0.0.50 or higher**

This advisory notice concerns backwards compatibility of Firmware Version 1.0.0.50.

Firmware Versions 1.0.0.50 and up is not compatible with DSP version 6 and below. Before upgrading your HI 6500 series unit, check to ensure you have DSP version 7 or higher. This DSP version 7 was release 1-30-2014.

Currently upgrades of the DSP version cannot be completed in the field and the unit would need to be sent in to the factory for the upgrade.